



Reliable, responsive,
and recognized since 1994.

CORPORATE HEADQUARTERS

114 Lincoln Ave.
Cobleskill, NY 12043
888-680-7974
www.firetesting.com

PRODUCT LISTING

Reference No. CS-A-1162-90min

Status: Current

Manufacturer:

Construction Specialties Inc
Acrovyn Door System, Building #3
6696 Route 405, Muncy, PA 17756

Product(s):

Acrovyn 90 min. Positive Pressure, Category A, Fire-Rated Door with Acrovyn 4000 faces and Acrovyn patented replaceable wood or engineered (SCL) stiles and Acrovyn or Stainless Steel edges, for use in listed steel frames.

Report:

Acrovyn 90 min. Positive Pressure, Category A, Fire-Rated Door with Acrovyn 4000 faces and Acrovyn patented replaceable wood or engineered (SCL) stiles and Acrovyn or Stainless Steel edges, for use in listed steel frames:

- Bonded Mineral Core (GP or Lexington)

Models: Flush

Single Swing: 4'-0" x 9'-0", Intumescent applied to the full width of the top rail only.

Standard Pairs and Double Egress: 8'-0" x 9'-0", Intumescent applied to the full width of the top rail, hinge and latch edge stiles, concealed behind the replaceable edge covers.

Standard Pairs require 3 point latching and Double Egress require 4 point latching.

Optional construction is available for 2 point latching for Pairs and Double Egress configurations.

90 min. approved for any listed and labeled glazing for up to 100 square inches of visible glass, with metal* or wood bead lite kits.

*Note: Includes wood veneer and Acrovyn wrapped metal lite kits.

Attribute Value

CSI Code 08 10 00 Doors and Frames

CSI Code 08 14 00 Wood Doors

Single Swing, Pairs, and Double Egress



Reliable, responsive,
and recognized since 1994.

CORPORATE HEADQUARTERS

114 Lincoln Ave.
Cobleskill, NY 12043
888-680-7974
www.firetesting.com

PRODUCT LISTING

Standards Tested To:

UL 10C, NFPA 252, ASTM E-2226 [UBC 7-2, and CAN4 S104 contain the criteria which is in UL 10C.]

Listing Category A doors: "No additional edge sealing system required for fire rating."

Guardian Test Reports:

GL 116211, 2/14/2012

Engineering Evaluation Report:

EER 17312 dated 3/13/2012