



Reliable, responsive,
and recognized since 1994.

CORPORATE HEADQUARTERS

114 Lincoln Ave.
Cobleskill, NY 12043
888-680-7974
www.firetesting.com

PRODUCT LISTING

Reference No. ASAGP-A-035517-HoseStream120

Status: Current

Manufacturer:

ASA, GP
4764 Hollins Ferry Road
Halethorpe, MD 21227

Product(s):

Hose Stream 120 Fire Shutter System

Report:

Guardian Test Report GL 035517; Test Report Date 4/18/17; Rev 5/5/17

Standards tested to: UL 10B, Standard for Fire Tests of Door Assemblies
ASTM E2226, 'Standard Practice for Application of Hose Stream'

Hose Stream 120 attained a fire protective rating of 90 minutes with hose stream.

Reference Documents: 2015 International Building Code (IBC) Table 716.5

The maximum transmitted temperature rise is not determined; 2015 IBC section 716.5.5 exception requires an approved automatic sprinkler system must be installed in accordance with Section 903.3.1.1 or 903.3.1.2 where the interior doors are used in exit stairways, ramps and exit passageways.

2015 IBC Table 716.5 permits a 1-1/2 hour rated fire door and fire assembly to be of a lower rating than the fire resistance rating of the fire barrier in which the assembly is located.